


PRESI GUIDE HARDNESS

HZ RANGE - LOAD CELLS



	HARDNESS TESTER	INDENTERS	TURRET	OBJECTIVES	INDENTERS
HZ2-2	Semi-automatic	Vickers or Knoop	Automatic	up to 4	1
HZ10-2	Semi-automatic	Vickers or Knoop	Automatic	up to 4	1
HZ30-2	Semi-automatic	Vickers or Knoop	Automatic	up to 4	1
HZ2-4	Automatic	Vickers or Knoop	Automatic	up to 4	1
HZ10-4	Automatic	Vickers or Knoop	Automatic	up to 4	1
HZ30-4	Automatic	Vickers or Knoop	Automatic	up to 4	1
HZ50-4	Automatic	Vickers and Knoop	Automatic	4	2